Thursday, 30/10/2008 9:18:31 AM Melanie Fauteux User **Process Sheet** : SQUARE TUBE : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Job Number : 41907 Estimate Number : 13425 : PB6743001203 Part Number PO Number : B6743001 P.17 S.O. No. : **Drawing Number** : 30/10/2008 This Issue : N/A Project Number Prsht Rev. : NC : B1 : 08/09/2008 Type : LARGE FAB ASSY **Drawing Revision** First Issue Material : 41789 Previous Run : 26/09/2008 Due Date Written By Checked & Approved By 08-06-26 new issue DD verified by:ec Comment : Est Rev:A Additional Product Job Number: Machine Or Operation: Description: Seq. #: 6061T6 SQ TUBE 1.00 x 1.00 X .120w 1.0 Comment: Qtv.: 1.6844 f(s)/Unit Total: 15.1597 f(s) 6061T6 SQ TUBE 1.00 X 0.005 . 120 batch: M 109928 SMALL & MEDIUM FAB RESOURCE 1 20 Comment: SMALL & MEDIUM FAB RESOURCE 1 1- cut to length as per dwg 2- make a 0.050" chamfer on both ends of tube 3- deburr INSPECT WORK TO CURRENT STEP 3.0 QC5 Comment: INSPECT WORK TO CURRENT STEP CONVENTIONAL MILLING MACHINE Comment: CONVENTIONAL MILLING MACHINE 1- drill holes as per dwg 2- make a 0.050" chamfer (100 degree) on both side of the 2 holes DIP 38/11/19 3- deburr INSPECT WORK TO CURRENT STEP QC5 5.0 (center Comment: INSPECT WORK TO CURRENT STEP

| 72 | * | | |
|----|-------------|-----|----|
| | 180° (18-1) | | |
| | | | |
| | | | |
| | | -5, | |
| | | | 54 |
| | | | |
| | .3 | | |
| | | | |
| | | | |
| | | | |
| | | | • |

Jay, 30/10/2008 9:18:31 AM anie Fauteux omer: CU-DAR001 Dart Helicopters Services

Process Sheet

Drawing Name: SQUARE TUBE

Job Number: 41907

Part Number: PB6743001203

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

PB6743001227

Bushing

Comment: Qty.:

Total: 2.0000 Each(s)/Unit

7.0

8.0

LARGE FAB 1



LARGE FABRICATION RESOURCE 1



12

Comment: LARGE FABRICATION RESOURCE 1

1- Weld assembly as per dwg

SMALL & MEDIUM FAB RESOURCE 1









Comment: SMALL & MEDIUM FAB RESOURCE 1

1- grind weld flush

2- deburr

VISUAL INSPECTION OF GROUND WELDS

QC10

INSPECTION OF GROUND WELDS Comment: VISUAL

INSPECT WORK TO CURRENT STEP




10.0

9.0

QC5

WORK TO CURRENT STEP Comment: INSPECT

PACKAGING RESOURCE #1



11.0

PACKAGING





Identify and Stock Location: 438



12.0

QC21

FINAL INSPECTION/W/O RELEASE




Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



| | 7 | | |
|--|---|----|-----|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | 3 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | 19 | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | • |
| | | | (4) |
| | | | * • |
| | | | |



| | | 4 |
|--|--|---|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Wiles I am a market and a marke | | |

| AR | TAÈR | SPACE LTD | , | | | Work Order: | 1 419 | ot. |
|-------|----------|---------------|---------------------|--------------|--------|-------------------------|--------|-----------|
| 181.5 | | Square Tube | 44 , | 16 14 | | Part Number: | PB6743 | 1001263 |
| A | | F . | | | | | Par | ge 1 of 1 |
| Inspe | ction Dv | vg: , Rev | : <u>R1</u> | | | | 1 143 | |
| | | FIRS | TARTICLE IN | SPECTIO | N CHE | CKLIST | | |
| | | . [] | First Artic | ele X | Proto | otype | | |
| | awing | Tolerance | Actual Dimension | Accept | Reject | Method of Inspection | Con | nments |
| 19. | 25 | ±0.030 | 19.252 | / | | | | |
| 1/. | | +0.030 | 11.33 | / | | | | |
| 7. | | ±0,030 | 7.93 | / | | | | |
| 0. | 1 | ±0,030 | 0.50 | / | | 134 | | |
| 3,4 | 10 | =0.030 | 3.40 | / | 1. | 1.2 | REF | 7 |
| \$.! | 56 | 1:0.030 | 0.570 | /, | | | Thru 1 | 12 |
| 305 | x45° | to,03 /= 1/2° | 105 X 45° | 2 | | | | |
| 1 | N 1 2 | | | | | | | |
| - | | | | | | | | |
| | | | 1. | ^ | | - A. | | |
| | | | | | 4 | 946 | | Tr. |
| | | | | | | | | 7. |
| 7 | | | | | | | | |
| | | | | | | | | *) = |
| | | | - | | | • | | |
| | | | | | . (| | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | - 3 | + | | | | |
| | | 1 - | | | | | | |
| | | 1 | | | | | | * |
| | | | 4 | | | | | |
| | | | | | 7 [- | | enl: | - |
| Measu | red by: | DIP | Audited by: | 111 | Pr | ototype Approv | _ | 19 |
| | Date: | 08/1/19 | Date: 0 | slulzy | | , Da | ite: | |
| Rev | Date | Change | | | | Revi | sed by | Approv |
| A | | New Issue | | | | KJ/JI | IM | |

200 p. - 120 p. - 120

| | 6 |
|--|-------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | - 130 |
| | |
| | |